

!FDC 4/8664 ZNY 4/8666 ZBW MA..AIRSPACE NANTUCKET,  
MASSACHUSETTS..TEMPORARY FLIGHT RESTRICTIONS. NOVEMBER 26-30, 2024  
LOCAL. THIS NOTAM REPLACES NOTAM 4/8132 DUE TO CHANGE IN TIMES.

PURSUANT TO 49 USC 40103(B)(3), THE FEDERAL AVIATION ADMINISTRATION  
(FAA) CLASSIFIES THE AIRSPACE DEFINED IN THIS NOTAM AS 'NTL DEFENSE  
AIRSPACE'. PILOTS WHO DO NOT ADHERE TO THE FOLLOWING PROC MAY BE  
INTERCEPTED, DETAINED AND INTERVIEWED BY LAW ENFORCEMENT/SECURITY  
PERSONNEL. ANY OF THE FOLLOWING ADDITIONAL ACTIONS MAY ALSO BE TAKEN  
AGAINST A PILOT WHO DOES NOT COMPLY WITH THE RQMNTS OR ANY SPECIAL  
INSTRUCTIONS OR PROC ANNOUNCED IN THIS NOTAM:

- A) THE FAA MAY TAKE ADMINISTRATIVE ACTION, INCLUDING IMPOSING CIVIL  
PENALTIES AND THE SUSPENSION OR REVOCATION OF AIRMEN CERTIFICATES;  
OR
- B) THE UNITED STATES GOVERNMENT MAY PURSUE CRIMINAL CHARGES,  
INCLUDING CHARGES UNDER 49 USC SECTION 46307; OR
- C) THE UNITED STATES GOVERNMENT MAY USE DEADLY FORCE AGAINST THE  
AIRBORNE ACFT, IF IT IS DETERMINED THAT THE ACFT POSES AN IMMINENT  
SECURITY THREAT.

PURSUANT TO 14 CFR 91.141, ALL ACFT FLT OPS INCLUDING REMOTE  
CONTROLLED ACFT OPS ARE PROHIBITED:

WI AN AREA DEFINED AS 30NM RADIUS OF 411512N0700338W (ACK237002.3)  
SFC-17999FT MSL  
EFFECTIVE 2411261945 UTC (1445 LOCAL 11/26/24) UNTIL 2412010100 UTC  
(2000 LOCAL 11/30/24).

WI AN AREA DEFINED AS 10NM RADIUS OF 411512N0700338W (ACK237002.3)  
SFC-17999FT MSL  
EFFECTIVE 2411261945 UTC (1445 LOCAL 11/26/24) UNTIL 2412010100 UTC  
(2000 LOCAL 11/30/24).

EXC AS SPECIFIED BLW AND/OR UNLESS AUTH BY ATC IN  
CONSULTATION WITH THE AIR TFC SECURITY COORDINATOR  
VIA THE DOMESTIC EVENTS NETWORK (DEN):

- A. ALL ACFT OPS WI THE 10NM RADIUS AREA(S) LISTED  
ABV, KNOWN AS THE INNER CORE(S), ARE PROHIBITED  
EXC FOR: APPROVED LAW ENFORCEMENT, MIL ACFT  
DIRECTLY SUPPORTING THE UNITED STATES SECRET  
SERVICE(USSS) AND THE OFFICE OF THE PRESIDENT OF  
THE UNITED STATES, APPROVED AIR AMBULANCE FLIGHTS,  
AND REGULARLY SCHEDULED COMMERCIAL PAX AND ALL -  
CARGO CARRIERS OPR UNDER ONE OF THE FOLLOWING TSA  
- APPROVED STANDARD SECURITY PROGRAMS / PROC AND  
ARE ARR INTO AND / OR DEP FM 14 CFR PART 139 AP:  
ACFT OPR STANDARD SECURITY PROGRAM(AOSSP), FULL  
ALL - CARGO ACFT OPR STANDARD SECURITY  
PROGRAM(FACAOSPP), MODEL SECURITY PROGRAM(MSP),  
TWELVE FIVE STANDARD SECURITY PROGRAM ALL  
CARGO(TFSSP - ALL CARGO), OR ALL - CARGO  
INTERNATIONAL SECURITY PROC(ACISP). ALL EMERGENCY

/ LIFE SAVING FLT (MEDICAL / LAW ENFORCEMENT /  
FIREFIGHTING) OPS MUST COORDINATE WITH ATC PRIOR  
TO THEIR DEP AT 603-594-5531 TO AVOID POTENTIAL  
DELAYS.

- B. FOR OPS WI THE AIRSPACE BTN THE 10NM RADIUS AND  
30NM RADIUS AREA(S) LISTED ABV, KNOWN AS THE OUTER  
RING(S): ALL ACFT OPR WI THE OUTER RING(S) LISTED  
ABV ARE LIMITED TO ACFT ARR OR DEP LOCAL  
AIRFIELDS, AND WORKLOAD PERMITTING, ATC MAY  
AUTHORIZE TRANSIT OPS. ACFT MAY NOT LOITER. ALL  
ACFT MUST BE ON AN ACT IFR OR FILED VFR FLT PLAN  
WITH A DISCRETE CODE ASSIGNED BY AN AIR TFC CTL  
(ATC) FAC. ACFT MUST BE SQUAWKING THE DISCRETE  
CODE PRIOR TO DEP AND AT ALL TIMES WHILE IN THE  
TFR AND MUST REMAIN IN TWO-WAY RADIO COM WITH ATC.
- C. ALL FLIGHT OPERATIONS NOT COVERED IN PARAGRAPH  
A. WITHIN THE 10 NMR AREA MUST BE SECURITY  
SCREENED BY TSA AT A GATEWAY AIRPORT PRIOR TO  
ARRIVING OR DEPARTING NANTUCKET AIRPORT (KACK).  
AIRCRAFT OPERATORS MUST REGISTER WITH THE  
TSA FOR GATEWAY SCREENING NO LESS THAN 24  
HOURS PRIOR TO THEIR SCHEDULED DEPARTURE TIME.  
RESERVATIONS FOR SCREENING MAY BEGIN ON  
11/25/2024 AND LAST THROUGH THE DURATION OF THE  
EVENT BY CALLING TSA AT 617-561-8030.
- D. GATEWAY AIRPORTS HAVE BEEN CREATED AT NANTUCKET  
(ACK), BOSTON (BOS), AND WHITE PLAINS (HPN) BY TSA  
TO ACCOMMODATE AIRCRAFT ARRIVING OR DEPARTING  
NANTUCKET AIRPORT (KACK).
- E. TSA SCREENING WILL NOT BE AVAILABLE TUESDAY  
241126. TSA SCREENING WILL BE AVAILABLE  
2411271300 UTC (0800 LOCAL 11/27/2024) TO  
2411272200 UTC (1700 LOCAL 11/27/2024).  
2411281300 UTC (0800 LOCAL 11/28/2024) TO  
2411282200 UTC (1700 LOCAL 11/28/2024).  
2411291300 UTC (0800 LOCAL 11/29/2024) TO  
2411292200 UTC (1700 LOCAL 11/29/2024).  
2411301300 UTC (0800 LOCAL 11/30/2024) TO  
2411302200 UTC (1700 LOCAL 11/30/2024). PILOTS,  
CREW AND PASSENGERS MUST PROVIDE VALID  
GOVERNMENT-ISSUED PHOTO IDENTIFICATION TO THE TSA  
AT THE GATEWAY AIRPORT. GATEWAY SCREENING WILL  
INCLUDE ID VERIFICATION AND VETTING OF ALL PILOTS,  
CREW AND PASSENGERS, SCREENING OF PERSONS AN  
BAGGAGE, AND INSPECTION OF THE AIRCRAFT. NO  
FIREARMS ON BOARD AIRCRAFT WILL BE AUTHORIZED. NO  
GIFT WRAPPED PACKAGES.
- F. ON DEPARTURE FROM A GATEWAY AIRPORT AIRCRAFT  
MUST MAINTAIN RADIO CONTACT WITH ATC AND  
CONTINUOUSLY SQUAWK AN ATC-ASSIGNED DISCRETE CODE.  
INTERMEDIATE STOPS WHILE ENROUTE ARE NOT  
AUTHORIZED UNLESS AN EMERGENCY EXISTS.

- G. THE FOLLOWING OPERATIONS ARE NOT AUTHORIZED WITHIN THIS TFR: FLIGHT TRAINING, PRACTICE INSTRUMENT APPROACHES, AEROBATIC FLIGHT, GLIDER OPERATIONS, PARACHUTE OPERATIONS, ULTRALIGHT, HANG GLIDING, BALLOON OPERATIONS, AGRICULTURE/CROP DUSTING, ANIMAL POPULATION CONTROL FLIGHT OPERATIONS, BANNER TOWING OPERATIONS, SIGHTSEEING OPERATIONS, MAINTENANCE TEST FLIGHTS, MODEL AIRCRAFT OPERATIONS, MODEL ROCKETRY, UNMANNED AIRCRAFT SYSTEMS (UAS), AND UTILITY AND PIPELINE SURVEY OPERATIONS.
- H. UAS OPERATORS WHO DO NOT COMPLY WITH APPLICABLE AIRSPACE RESTRICTIONS ARE WARNED THAT PURSUANT TO 10 U.S.C. SECTION 130I AND 6 U.S.C. SECTION 124N, THE DEPARTMENT OF DEFENSE (DOD), THE DEPARTMENT OF HOMELAND SECURITY (DHS) OR THE DEPARTMENT OF JUSTICE (DOJ) MAY TAKE SECURITY ACTION THAT RESULTS IN THE INTERFERENCE, DISRUPTION, SEIZURE, DAMAGING, OR DESTRUCTION OF UNMANNED AIRCRAFT DEEMED TO POSE A CREDIBLE SAFETY OR SECURITY THREAT TO PROTECTED PERSONNEL, FACILITIES, OR ASSETS.
- I. THE SYSTEM OPERATIONS SUPPORT CENTER (SOSC), IS THE COORDINATION FACILITY FOR GOVERNMENT AGENCIES AND IS AVAILABLE DAILY FROM 0700-2300 EASTERN, PHONE 202-267-8276 FOR COORDINATION.
- J. THE FAA RECOMMENDS THAT ALL AIRCRAFT OPERATORS CHECK NOTAMS FREQUENTLY FOR POSSIBLE CHANGES TO THIS TFR PRIOR TO OPERATIONS WITHIN THIS REGION. OPERATORS MAY REVIEW THE TFR DETAILS ON THE INTERNET AT [HTTPS://TFR.FAA.GOV/](https://tfr.faa.gov/) OR [HTTPS://WWW.1800WXBRIEF.COM](https://www.1800wxbrief.com). IF QUESTIONS REMAIN, CONTACT FLIGHT SERVICE AT 800-992-7433.

2411261945-2412010100